

## **CONVERTISSEUR USB - SERIE**



## Guide d'installation rapide

(DA-70146-BA)

## Comment utiliser notre produit

Étape 1 : Insérez le CD du pilote de ce produit dans le lecteur CD-ROM

Étape 2 : Branchez le dispositif dans un port USB de votre PC, et utilisez l'assistant nouveau matériel trouvé, reportez-vous à la figure suivante :



Étape 3 : Sélectionnez "No, not this time (Non, pas cette fois-ci)", cliquez sur "Next (Suivant)" pour continuer.



Étape 4 : Sélectionnez "Install from a list or specific location (Advanced) (Installer à partir d'une liste ou un emplacement spécifique (Avancé))", cliquez sur "Next (Suivant)" pour continuer.

Found New Hardware Wizard		
Please choose your search and installation options.		
<ul> <li>Search for the best driver in these locations.</li> </ul>		
Use the check boxes below to limit or expand the default search, which includes local paths and removable media. The best driver found will be installed.		
Search removable media (floppy, CD-ROM)		
Include this location in the search:		
i:\ Browse		
O Don't search. I will choose the driver to install.		
Choose this option to select the device driver from a list. Windows does not guarantee that the driver you choose will be the best match for your hardware.		
< Back Next > Cancel		

Étape 5 : Sélectionnez "Search removable media (floppy, CD-ROD...) (Rechercher le support amovible (disquette, CD-ROM ...))", cliquez sur "Next (Suivant)" pour continuer.

Found New Hardware Wizard	
Please wait while the wizard searches.	
usb serial converter	S.
	< Back Next > Cancel

Étape 6 : Recherche automatique du pilote correspondant sur le CD.

Found New Hardware Wizard			
Please select the best match for your hardware from the list below.			
USB Serial Converter			
Description Version Manufacturer Location			
USB Serial Converter 2.2.4.0 FTDI i:\usb 2.0 to rs232 converter\w			
WUSB Serial Converter 2.2.4.0 FTDI i:\usb 2.0 to rs232 cable\win2C			
This driver is digitally signed. <u>Tell me why driver signing is important</u>			
<pre></pre>			

Étape 7 : Vous trouverez deux types de matériel, un pour le Convertisseur USB 2.0 -RS232, l'autre pour l'USB 2.0 - câble RS232 Sélectionnez le pilote correspondant en fonction de votre produit, cliquez sur "Next (Suivant)" pour continuer.

Found New Hardware Wizard	
Please wait while the wizard instal	Is the software
USB Serial Converter	
ftd2xx.dll To C:\WINDOWS\sys	wow64
	< Back Next > Cancel

Étape 8 : L'assistant lance l'installation et copie les fichiers sur votre système



Étape 9 : Cliquez sur "Finish (Terminer)" pour terminer l'installation.



Étape 10 : Trouvez le nouveau port com.

Found New Hardware Wiz	ard
	Welcome to the Found New Hardware Wizard
	Windows will search for current and updated software by looking on your computer, on the hardware installation CD, or on the Windows Update Web site (with your permission). Online privacy information
	Can Windows connect to Windows Update to search for software?
	○ Yes, this time only
	Yes, now and every time I connect a device
	💽 No, not this time
	Click Next to continue.
	< Back Next > Cancel

Étape 11 : Sélectionnez "No, not this time (Non, pas cette fois-ci)", cliquez sur "Next (Suivant)" pour continuer.



Étape 12 : Sélectionnez "Install from a list or specific location (Advanced) (Installer à partir d'une liste ou un emplacement spécifique (Avancé))", cliquez sur "Next (Suivant)" pour continuer.

Found New Hardware Wizard			
Please choose your search and installation options.			
<ul> <li>Search for the best driver in these locations.</li> </ul>			
Use the check boxes below to limit or expand the default search, which includes local paths and removable media. The best driver found will be installed.			
Search removable media (floppy, CD-ROM)			
Include this location in the search:			
i:\ Browse			
O Don't search. I will choose the driver to install.			
Choose this option to select the device driver from a list. Windows does not guarantee that the driver you choose will be the best match for your hardware.			
< Back Next > Cancel			

Étape 13 : Sélectionnez "Search removable media (Floppy, CD-ROM...) (Rechercher le support amovible (disquette, CD-ROM ...))", cliquez sur "Next (Suivant)" pour continuer.

Found New H	lardware Wizard
Please wai	it while the wizard searches
2	USB Serial Port
	<pre></pre>

Étape 14 : Recherche automatique du pilote correspondant sur le CD.

Found New Hardware Wizard			
Please select the best match for your hardware from the list below.			
USB Serial Port			
Description Version Manufacturer Location			
USB Serial Port 2.2.4.0 FTDI i:\usb 2.0 to rs232 converter\win200			
WUSB Serial Port 2.2.4.0 FTDI i:\usb 2.0 to rs232 cable\win2000_xr			
This driver is digitally signed. <u>Tell me why driver signing is important</u>			
< Back Next > Cancel			

Étape 15 : Sélectionnez le pilote correspondant en fonction de votre produit, cliquez sur "Next (Suivant)" pour continuer.

Found New	Hardware Wizard			
Please wa	it while the wizard installs the	e software		
Ţ	USB Serial Port			
	FTLang.dll To C:\WINDOWS\system32	2		
		< Back	Next >	Cancel

Étape 16 : L'assistant lance l'installation et copie les fichiers sur votre système.



Étape 17 : Cliquez sur "Finish (Terminer)" pour terminer l'installation et fermer l'assistant.



Étape 18 : Votre nouveau matériel est installé et prêt à être utilisé.

Þ		
My Docume	ents	
My Comp	Open	Contraction of the local division of the loc
	Explore	
-	Search	
	Manage	
Mu Nah	Map Network Drive	
Place	Disconnect Network Drive	
	Create Shortcut	
	Delete	
Recycle –	Rename	
	Properties	

Étape 19 : Si vous voulez le voir, cliquez avec le bouton droit sur "my computer (Poste de travail)", puis cliquez sur "Properties (Propriétés)".

Syster	n Restore	Automa	atic Updates	Remote
General	Comp	outer Name	Hardware	Advanced
Device I	Manager			
Ż	The Device M on your comp properties of a	Managerlists all Juter. Use the D any device.	the hardware devic evice Manager to c	ces installed change the
		5	Device M	lanager
Drivers -	1			
Drivers	Driving Signin compatible wi how Windows	ng lets you make th Windows. W s connects to W	e sure that installed indows Update lets /indows Update for	drivers are s you set up drivers.
Drivers -	Driving Signin compatible wi how Windows Driver	ng lets you make th Windows. W s connects to W Signing	e sure that installed indows Update lets /indows Update for Windows	drivers are s you set up drivers. Update
Drivers -	Driving Signin compatible wi how Windows Driver	ng lets you make th Windows. W s connects to W Signing	e sure that installed indows Update lets /indows Update for Windows	drivers are s you set up drivers. Update
Drivers - Example Hardwar	Driving Signin compatible wi how Windows Driver Profiles Hardware pro different hardw	ng lets you makk th Windows. W s connects to W Signing files provide a w ware configurat	e sure that installed indows Update lets /indows Update for Windows way for you to set u ions.	drivers are s you set up drivers. Update p and store

Étape 20 : Sélectionnez "Device Manager (Gestionnaire de périphériques)" dans l'onglet "Hardware (matériel)" de la fenêtre "System Properties (Propriétés Système)", cliquez dessus, vous pouvez voir les périphériques matériels installés sur votre ordinateur, reportez-vous à la figure suivante :



Étape 21 : Installation terminée.

Remarques :

Après l'installation, si vous pouvez voir "USB Serial Converter (Convertisseur USB – série)" dans "Device Manager (Gestionnaire de périphériques)", mais vous ne pouvez pas voir "USB Serial Port (COM3) (Port série USB (COM3))", continuez avec les étapes suivantes.



🗄 🌆 Human Interface Dev	ices				
🗄 🗃 IDE ATA/ATAPI contri	ollers				
主 🦢 Keyboards					
🗄 🐚 Mice and other pointir	ng devices				
🗄 🚰 Other devices					
🖻 🝠 Ports (COM & LPT)					
Communications P	Port (COM1)				
Communications F	Communications Port (COM2)				
🔄 🖳 🍠 Printer Port (LPT1	)				
🗄 🦔 Processors					
🗄 🎱 Sound, video and gan	ne controllers				
🗄 🧕 System devices					
🖻 🥰 Universal Serial Bus co	ontrollers				
😪 Standard Univers	al PCI to USB Host Controller				
😪 Standard Univers	al PCI to USB Host Controller				
😋 Standard Univers	al PCI to USB Host Controller				
😽 Standard Univers	al PCI to USB Host Controller				
😋 USB Root Hub					
😋 USB Root Hub					
😋 USB Root Hub					
😴 USB Root Hub					
🛶 😋 USB Serial Conver	ter.				
	Update Driver				
	Disable				
	Uninstall				
	Scan for hardware changes				
	Properties				

Étape A : Cliquez avec le bouton droit sur "USB Serial Converter (Convertisseur USB – série)", puis cliquez sur "Properties (Propriétés)".

USB Seri	al Convert	er Properties	? 🛛
General	Advanced	Power Management Driver	
- Cor Use	USB Serial	Converter is to override normal device confi	guration
		OK Ca	ncel Help

Étape B : Sélectionnez "Load VCP (Charger VCP)" dans l'onglet "Advanced (Avancé)", cliquez sur "OK".

Étape C : Retirez le convertisseur USB - RS232 de votre ordinateur. Rebranchez le dispositif dans un port USB de votre PC, ça doit marcher, reportez-vous à la figure suivante :



Félicitations, l'installation est réussie.

Désinstaller le pilote

:

1. Ouvrez les pilotes de ce produit, reportez-vous à la figure suivante :



2. Double cliquez sur "FTClen.exe", l'interface suivante apparaît :

	••
🌮 FTDI Clean Utility V1.0	- ×
<b>FTDI</b> Chip	
VID (Hex) FTDI	Clean System
PID (Hex)	Exit
Status: Ready	

3. Double cliquez sur "Clean System (Nettoyer le système)", l'interface suivante apparaît



4. Déconnectez le convertisseur USB 2.0 - RS232 de l'ordinateur, cliquez sur "ok", l'interface suivante apparaît, cliquez sur "Yes" (Oui).

Confirm	Uni M FTDI Clean Utility V1.0	- ×
?	You are about to uninstall all FTDI drivers for VID 0x0403 and all PIDs. Do you want to continue?	
	FTDI	Clean System
	Windows XP Status: Ready	Exit

5. Cliquez sur "No (Non)" pour désinstaller le pilote.

	🗊 FTDI Clean Utility V1.0	- ×
Confirm	*TDI	
? Do	you want to cancel driver uninstallation?	
	Yes No	
	FTDI	Clean System
	PID (Hex)	Exit
	Windows XP Status: Ready	

6. Lorsque la désinstallation est terminée, cliquez sur "Exit (quitter)" pour quitter l'application de désinstallation.

🐺 FTDI Clean Utility V1.0	- 10.0	×
<b>FTDI</b> Chip		
VID (Hex)		
PID (Hex)	Exit	
Windows XP Status: System clean completed		_