

ПОСЛЕДОВАТЕЛЬНЫЙ USB

КОНВЕРТЕР



Инструкция по быстрой установке

(DA-70146-BA)

Добро пожаловать к нашему изделию

Шаг 1: Вставьте CD драйвер этого изделия в CD-ROM

Шаг 2: Подключите изделие к свободному порту USB вашего ПК, и обнаружите «hardware wizard» (диспетчер аппаратуры), см. ниже:



Шаг 3: Выберите "No, not this time" (Не сейчас), кликните "Next" (Далее) для продолжения.

Found New Hardware Wizard		
Image: Note of the i		
 Install from a list or specific location (Advanced) Click Next to continue. 		
< Back Next > Cancel		

Шаг 4: Выберите "Install from a list or specific location (Advanced)" (Установить из специального списка (Расширенный)), кликните "Next" (Далее) для продолжения.

Found New Hardware Wizard		
Please choose your search and installation options.		
Search for the best driver in these locations. Use the check boxes below to limit or expand the default search, which includes local paths and removable media. The best driver found will be installed. Search removable media (floppy, CD-ROM)		
Include this location in the search:		
Choose this option to select the device driver from a list. Windows does not guarantee that the driver you choose will be the best match for your hardware.		
< Back Next > Cancel		

Шаг 5: Выберите "Search removable media (floppy, CD-ROD...)" (Найдите съемный (флоппи, CD-ROD)), кликните "Next" (Далее) для продолжения.

Found New Hardware Wizard		
Please wait while the wizard searches		
usb serial converter		
< B2	ack Next > Cancel	

Шаг 6: Автопоиск соответствующего драйвера на СD.

Found New Hardware Wizard			
Please select the best match for your hardware from the list below.			
USB Serial Converter			
Description Version Manufacturer Location			
USB Serial Converter 2.2.4.0 FTDI i:\usb 2.0 to rs232 converter\w			
WUSB Serial Converter 2.2.4.0 FTDI i:\usb 2.0 to rs232 cable\win20			
This driver is digitally signed. <u>Tell me why driver signing is important</u> < Back Next > Cancel			

Шаг 7: Появятся два диспетчера аппаратуры, один для USB 2.0 TO RS232 конвертера, другой для USB 2.0 TO RS232 кабеля. Выберите нужный драйвер для вашего изделия и кликните "Next" (Далее) для продолжения.

Found New Hardware Wizard		
Please wait while the wizard installs the software		
¢	USB Serial Converter	
	6 ftd2xx.dll To C:\WINDOWS\syswow64	
	< Back Next > Cancel	

Шаг 8: Диспетчер начал установку и копирование файла в вашу систему

Found New Hardware Wizard		
Found New Hardware Wiz	<image/> <image/> <image/>	
	Click Finish to close the wizard.	
	< Back Finish Cancel	

Шаг 9: Кликните "Finish" (Окончание) для закрытия диспетчера.



Шаг 10: Найдите новый сот порт.

Found New Hardware Wizard			
	Welcome to the Found New Hardware Wizard Windows will search for current and updated software by looking on your computer, on the hardware installation CD, or on the Windows Update Web site (with your permission). Online privacy information		
	Can Windows connect to Windows Update to search for software?		
	◯ Yes, this time only		
	Yes, now and every time I connect a device		
No, hot this time			
	Click Next to continue.		
	< Back Next > Cancel		

Шаг 11: Выберите "No, not this time" (Не сейчас), кликните "Next" (Далее) для продолжения.

Found New Hardware Wizard		
	This wizard helps you install software for: USB Serial Port If your hardware came with an installation CD or floppy disk, insert it now.	
	What do you want the wizard to do?	
	 Install the software automatically (Recommended) 	
	 Install from a list or specific location (Advanced) Click Next to continue. 	
	< Back Next > Cancel	

Шаг 12: Выберите "Install from a list or specific location (Advanced) (Установить из отдельного списка (Расширенный)), кликните "Next" (Далее) для продолжения.

Found New Hardware Wizard		
Please choose your search and installation options.		
 Search for the best driver in these locations. 		
Use the check boxes below to limit or expand the default search, which includes local paths and removable media. The best driver found will be installed.		
Search removable media (floppy, CD-ROM)		
Include this location in the search:		
i:\ Browse		
O Don't search. I will choose the driver to install.		
Choose this option to select the device driver from a list. Windows does not guarantee that the driver you choose will be the best match for your hardware.		
< Back Next > Cancel		

Step 13: Выберите "Search removable media (Floppy, CD-ROM...)" (Найдите съемный

(флоппи, CD-ROM...), кликните "Next" (Далее) для продолжения.

Found New Hardware Wizard		
Please wait while the wizard searche	s	
USB Serial Port		
	< Back Next > Cancel	

Шаг 14: Автопоиск соответствующего драйвера на CD.

Found N	Found New Hardware Wizard			
Please select the best match for your hardware from the list below.			E)	
USB Serial Port				
	Description	Version Manufacturer	Location	
Ğ	😻 USB Serial Port	2.2.4.0 FTDI	i:\usb 2.0 to rs232 converter\w	vin200
G	💱 USB Serial Port	2.2.4.0 FTDI	i:\usb 2.0 to rs232 cable\win20)000_xt
<	:			>
This driver is digitally signed. <u>Tell me why driver signing is important</u>				
			< Back Next >	Cancel

Шаг 15: Выберите драйвер для вашего изделия, кликните "Next" (Далее) для продолжения.

Found New Hardware Wizard		
Please wait while the wizard installs the	software	
USB Serial Port		
FTLang.dll To C:\WINDOWS\system32		
	< Back Next > Cancel	

Шаг 16: Диспетчер начал установку и копирование файла в вашу систему.



Шаг 17: Установка закончена, кликните "Finish" (Окончание) для закрытия диспетчера.

Found New Hardware Your new hardware is installed an	nd ready to	use.
	EN	👟 🧐 🧐 🖉 4:34 PM

Шаг 18: Ваше устройство принято и готово для пользования.



Шаг 19: Если хотите увидеть его, кликните правой кнопкой "my computer" (мой компьютер), затем кликните "Properties" (Свойства).

System	m Restore	Automat	ic Updates 🛛 🗍	Remote
General	l Compu	ter Name	Hardware	Advanced
Device	Manager			
Ż	The Device Ma on your compu properties of ar	anagerlists all t ter. Use the De ny device.	he hardware device vice Manager to cl	es installed hange the
		(Device Ma	anager
Drivers				
	Driving Signing compatible with how Windows	lets you make Windows, Wir connects to W	sure that installed o ndows Update lets indows Update for	drivers are you set up drivers.
	Driver S	igning	Windows L	Jpdate
Hardwa	Driver S	igning	Windows L	Jpdate
Hardwa	Driver S re Profiles Hardware profil different hardw	igning les provide a w are configuratio	Windows L ay for you to set up ins.	Jpdate

Шаг 20: Выберите "Device Manager" (Диспетчер устройств) в закладке "Hardware" (Аппаратура) интерфейса "System Properties" (Свойства системы), кликните его, и вы увидите устройства, подключенные к вашему компьютеру, обратитесь к следующему списку:



Шаг 21: Установка закончена.

Примечание:

После установки, если вы видите строку "USB Serial Converter" (Последовательный USB конвертер) из "Device Manager" (Диспетчер устройств), но не можете видеть "USB Serial Port (COM3)", (USB последовательный порт (COM3)), проделайте следующие шаги:



+	Human Interface Devic	es	
Ð 🔒	IDE ATA/ATAPI control	llers	
÷ 🍉	Keyboards		
÷ 🖒	Mice and other pointing	g devices	
± 🌮	Other devices		
0.7	Ports (COM & LPT)		
-	Communications Pc	ort (COM1)	
-	Z Communications Pc	ort (COM2)	
- L.	🍠 Printer Port (LPT1)		
+	Processors		
÷ Q	Sound, video and game	e controllers	
Ð 😼	System devices		
	Universal Serial Bus cor	ntrollers	
	😴 Standard Universal	PCI to USB Host Controller	
	🈴 Standard Universal	PCI to USB Host Controller	
	🈴 Standard Universal	PCI to USB Host Controller	
	😴 Standard Universal	PCI to USB Host Controller	
	😴 USB Root Hub		
	😴 USB Root Hub		
	😴 USB Root Hub		
	😴 USB Root Hub		
8	😪 USB Serial Convert	er in the prime	1
		Update Driver	1
		Disable	
	_	Uninstall	
	_	Scan for hardware changes	
		Properties	
			-

Шаг А: Кликните правой кнопкой "USB Serial Converter" (USB последовательный конвертер), затем кликните "Properties" (Свойства).

SB Seri	al Convert	er Properties	? 🕻
General	Advanced	Power Management Driver	
Con Use	USB Serial figuration these setting Load VCP	Converter is to override normal device configu	Iration
			el Helo

Шаг В: Выберите"Load VCP" (Загрузить VCP) в закладке "Advanced" (Расширеный), кликните "OK".

Шаг C: Отключите «USB TO RS232» (USB на RS232) на вашем компьютере. Снова подключите устройство к тому же порту USB вашего ПК, теперь все в порядке, смотрите список:



Поздравляем, установка завершена.

Удалить драйвер

1, Откройте драйверы изделия, см. ниже:



2 , Дважды кликните "FTClen.exe" (FTClen.exe), появится следующий интерфейс:

🀙 FTDI Clean Utility V1.0	_ ×
FTDI Chip	
VID (Hex) FTDI	Clean Sustem
PID (Hex)	Exit
Status: Ready	

3 , кликните "Clean System" (Очистить систему), появится следующий интерфейс :



4 [,] На «Disconnect USB 2.0 To rs232 device from the pc» [,] (отключить USB 2.0 на rs232) кликните "ok ", - появится следующий интерфейс, кликните "Yes" (Да)

	Uni FTI	FTDI Clean Utility V1.0	- ×
Confirm		×	
2	You are about to Do you want to	o uninstall all FTDI drivers for VID 0x0403 and all PIDs.	
		Yes No	
^		FTDI -	Clean System
		PID (Hex)	
			Exit
		Windows XP	
		Status: Ready	

5, кликните "No" (Нет) для удаления диска

TI FTI	🗊 FTDI Clean Utility V1.0	-	×
Confirm	× TDI		
? Do	you want to cancel driver uninstallation?		
	FTDI		Ĩ
	PID (Hex)	Exit	
	Windows XP Status: Ready		

6, После окончания, кликните "Exit" (Выйти) для окончания процедуры удаления.

